# MATERIAL SAFETY DATA SHEET

### SECTION 1 PRODUCT NAME AND COMPANY IDENTIFICATION

PRODCUT NAME: Vinflex

MANUFACTURER'S NAME: Webster Fabric

MANUFACTURER'S ADDRESS: 582 Goddard Ave.

Chesterfield, Mo. 63005

EMERGENCY TELEPHONE NUMBER: 314-532-1614

TELEPHONE NUMBER: 314-532-1614

**DATE PREPARED**: 5-1-99

### **SECTION 2 HAZARDOUS COMPONETS**

Benzenedicarboxlic acid CAS-68515-49-1 Vinyl Chloride<.001%PBL CAS-75-01-4

### SECTION 3 PHYSICAL/CHEMICAL CHARACTERISTICS

BOILING POINT-----NA
VAPOR PRESSURE----NA
VAPOR DENSITY----NA
SOLUBILITY IN WATER---NA
APPEARANCE AND ODOR---NA
SURFACE GRAVITY---NA
MELTING POINT---NA
EVAPORATION RATE---NA

### SECTION 4 FIRE AND EXPLOSION HAZARDS

FLASH POINT-----NA FLAMMABLE LIMITS----NA

EXTINUISHING MEDIA------WATER, ABC DRY CHEMICAL

SPECIAL FIRE FIGHTING PROCEDURES-----FIREFIGHTERS SHOULD WEAR SELF-

CONTAINED BREATHING APPARATUS (SCBA)

UNUSUAL FIRE AND EXPLOSION HAZARDS----NA

## **SECTION 5 REACTIVITY DATA**

STABILITY-----STABLE

CONDITIONS TO AVOID-----TEMPERATURES ABOVE 600 DEGREES F
INCOMPATILITY (MATERIALS TO AVOID)----STRONG OXIDIZING AGENTS
HAZARDOUS DECOMPOSITION OR BYPRODUCTS—NITROUS GASSES, HYDROGEN

CYANIDE AND CARBON MONOXIDE ARE POSSIBLE DECOMPOSTION BY PRODUCTS

POLYMERIZATION---WILL NOT OCCUR

## SECTION 6 HEALTH HAZARD DATA

PRIMARY ROUTES OF ENTRY AND FIRST AID PROCEDURES:

**SKIN CONTACT:** SHOULD MOLTEN MATERIAL CONTACT THE SKIN DURING PROCESSING, COOL AFFECTED AREA WITH WATER AND EXCLUDE AIR. TREAT FOR BURN.

INHALATION: NEGLIGIBLE HAZARD AT AMBIENT TEMPERATURE (0 TO 100 DEGREES F, - 18 TO +38 DEGREES C). VAPORS AND/OR AEROSOLS WHICH MAY BE FORMED AT ELEVATED TEMPERATURS MAY BE IRRITATIONF TO THE EYES ANS RESPIRATORY TRACT. IF A PROBLEM DEVLOPS REMOVE THE PERSON TO FRESH AIR AND SUPPLY OXYGEN IF NECESSARY

**INGESTION:** MINIMAL TOXICITY. FIRST AID IS NOT NECESSARY

EYE CONTACT: THIS PRODUCT IS AN INERT SOLID. IF IN EYE REMOVE AS ONE WOULD

REMOVE ANY FOREIGN OBJECT.

THRESHOLD LIMIT VALUE: NO ESTABLISHED VALUE. PRODUCT IS INERT

**EFFECTS OF OVEREXPOSURE:** NA

### SECTION 7 SPILL OR LEAK PROCEDURES

**CLEAN UP:** ALLOW TO COOL, SWEEP OR SCRAP INTO SECURE CONTAINERS FOR DISPOSAL.

**WASTE DISPOSAL:** DISPOSE OF IN ACCORDANE WITH LOCAL, STATE AND FEDERAL REGULATIONS.

#### SECTION 8 STORAGE AND HANDLING

**PRECAUTIONS TO BE TAKEN IN HANDLING AND STORGAE:** STORE IN A COOL DRY AREA AWAY FROM DIRECT SUNLIGHT.

SECTION 9 SPECIAL PROTESTION INFORAMTION

RESPIRATORY PROTECTION: -----NA

LOCAL EXHAUST: ----- NA

PROTECTIVE GLOVES: -----NOT NEEDED

EYE PROTECTION: -----USE OF EYE PROTECTION DURING PROCESSING IS

RECOMMENDED WITH ACCEPTED INDUSTRY SAFETY PROCEDURES.

WORK/HYGENIC PRACTICES: PRACTICE GOOD HYGIENE AFTER HANDLING.

SECTION 10 REGULATORY INFORAMTION

TSCA INVENTORY